

**Government of Telangana  
Roads & Buildings Department**

**From**

Sri P. Suresh Babu, M.Tech.,  
District (R&B) Officer,  
Hanumakonda.

**To**

The Secretary/ Correspondent,  
TEJASWI PUBLIC SCHOOL  
H.No.23-6-128/35/25,Durgadevi Colony  
Hunter Road , Hanumakonda.



**Letter.No. DB/ D1/R&B/HNK/2024-25/440**

**Date:22-06-2024.**

**Gentleman,**

**Sub:-** District (R&B) Office,Hanumakonda-Submission of Building Structural Soundness report of Tejaswi Public School, Located In House No. 23-6-128/35/25,Durgadevi Colony, Hunter Road, Hanumakonda District -Issuance –Regarding.

**Ref:-** 1. Your letter No.-Nil-,HNK/2024-25, Date.24-05-2024.  
2. Deputy Executive Engineer(R&B) Buildings Sub-Division,Hnk Letter.No.DEE/R&B/HNK/2024-25, Date:20-06-2024.

--o0o--

Adverting to your letter vide reference 1st cited, it is inform that, the building belonging to **Tejaswi Public School, located in H.No. 23-6-128/35/25, Durgadevi Colony,Hunter Road,Hanumakonda District** has been inspected by the Deputy Executive Engineer (R&B) Buildings Sub-Division, Hanumakonda on 20-06-2024 and reported that, the above building is found Structurally sound vide reference 2<sup>nd</sup> cited.

Accordingly the structural soundness certificate for the above building is issued for one year **i.e.**, for the academic year 2024-25

Yours faithfully,

*P. Suresh Babu*  
22/6/2024  
**District R&B Officer  
Hanumakonda**

Copy to the Deputy Executive Engineer(R&B),Buildings Sub-Division, Hanumakonda for information.